



SERVICE BULLETIN

Health Imaging Products

Eastman Kodak Company, Health Imaging, Rochester, NY 14650

SERVICE BULLETIN NO. 216

**Revised February 2004
Supersedes May 1995**

3228 *Kodak X-Omat 480 RA PROCESSOR*

Update from Previous Version

New part number for the Dryer Belt (see Table below.)

Dryer Transport Enhancement Kit Available

The purpose of the Dryer Transport Enhancement Kit is to provide increased drive to the DRYER EXIT TURNAROUND ASSEMBLY on the *Kodak X-Omat 480 RA PROCESSOR*. This will be helpful for processors that have experienced film jams in the DRYER EXIT TURNAROUND ASSEMBLY, or have difficulty transporting roll film.

Installation time is approximately 1 hour.

Order Kit 5B6862 from Service Parts Management, Rochester, New York.

KIT 5B6862 includes the following:

Quantity	Part No.	Description
1	1C7648	BEARING BLOCK ASSEMBLY
1	5B6865	SCREW - Idler Pulley
1	852623	NUT
1	535009	LOCK WASHER
1	107485	WASHER
1	5B6028	DRIVE ROLLER ASSEMBLY
1	1C7649	CAP - Bearing Block
1	8B7344	DRIVE BELT (New P/N)
1	5B6349	INSTALLATION INSTRUCTIONS

Debbie Trubatch, Service Engineer – Rochester, NY

For more information please contact:

**Eastman Kodak Company
Health Imaging
1-800-328-2910 (U. S. Only)
651-393-1728 (Outside the U.S.A.)**

Kodak and *X-Omat* are trademarks.

Printed in the USA. Pub No. N-262

©Eastman Kodak Company, 2004
Rochester, NY 14650

HEALTH IMAGING

